




cm
inch




1




2




3




1







2




3






Ax34  $\Phi 8 \times \frac{25}{1.2}$	Ex1  $\Phi M4 \times \frac{22}{0.8}$	Gx14  $\frac{10 \times 10}{0.4 \times 0.4}$	Jx1 
Dx50  $3.5 \times \frac{25}{0.99}$	Fx2  $3.5 \times \frac{14}{0.6}$	Ix18 	Kx1 
Zx04  $\Phi 8 \times \frac{40}{1.0}$			



1



Ax30	
Ix22	




2




Dx4	
-----	---


3



Dx6




4



Dx6




5



Dx2






6



Gx14




7




Ax4	
Dx12	

8




Dx10		Ex1		Kx1	
------	--	-----	--	-----	--

9



Dx10		Fx2		Jx1	
------	---	-----	---	-----	--

10



Zx4	
-----	---