



15



A x16 M x16




16



Q x28




17




Q x28




18




utilizar cola nas cavilhas




I x1




19



A x8 B x10



20



C x12 H x4

