

















A x 32 ϕ 6 x $\frac{30}{1.2}$



B x 4 C x 4 D x 17 E x 8 F x 14 $\phi 6 \times \frac{15}{0.6} \quad \phi 6 \times \frac{40}{1.6} \quad \phi 4 \times \frac{25}{1.0} \quad \phi 5 \times \frac{40}{1.6} \quad \phi 7 \times \frac{70}{2.8}$

G x 1





1 x 2











H x 9

 $\phi 4 \times \frac{30}{1.2}$

J x 2

K x 16

L x 2

M x 11

 ϕ 3 x $\frac{20}{0.8}$

 ϕ 3 x $\frac{16}{0.6}$













N x 4 Ø8 x 25 1

O x 1

P x 2

 $\phi 4 \times \frac{40}{1.6}$

Q x 4

R x 14



T x 1






U x 1





V x 2





W x 2



































D x 7		ф4 x <u>25</u> 1.0
Vx2		
M x 4	*)	ϕ 3 x $\frac{16}{0.6}$
T x 1	\bigcirc	







M x 1	30000	$\phi 3 \times \frac{16}{0.6}$
Ux1	0	

