




cm
inch




1




2




3




1










2




3






Ax42  $\Phi 8 \times \frac{25}{1.0}$	Fx14  $3.5 \times \frac{14}{0.6}$	Kx1 	Px1  $\Phi 4.0 \times \frac{16}{0.6}$
Bx6  $\Phi 8 \times \frac{20}{0.8}$	Gx31  $\frac{8 \times 8}{0.3 \times 0.3}$	Lx2 	Rx2 
Cx2  $4.0 \times \frac{40}{1.6}$	Hx4 	Mx5 	Zx6  $\Phi 8 \times \frac{40}{1.0}$
Dx74  $3.5 \times \frac{25}{0.99}$	Ix32 	Nx2 	
Ex1  $\Phi M4 \times \frac{22}{0.8}$	Jx3 	Ox1 	


1



2




3



Dx6




4




Dx9




5




6



7




8




Dx18



9




10




Fx4	
Lx2	

11



12 x3



Dx30




Fx6



Jx3




13



Ax6





14



Zx6






15



Nx1	
Ox1	
Px1	

16



Nx1	
-----	--