








cm
inch


1




2




3




1









2




3






Ax40  $\Phi 8 \times \frac{25}{1.0}$	Fx2  $3.5 \times \frac{14}{0.6}$	lx20 	Nx2 
Dx57  $3.5 \times \frac{25}{0.99}$	Gx30  $\frac{8 \times 8}{0.3 \times 0.3}$	Jx1 	Ox1 
Ex1  $\Phi M4 \times \frac{22}{0.8}$	Hx4 	Kx1 	Px1  $\Phi 4.0 \times \frac{16}{0.6}$
Zx4  $\Phi 8 \times \frac{40}{1.0}$			


1



2




3



Dx6




4




Dx6




5



Dx3




6




Gx30




7




Dx12



8



9



Dx10




Ex1



Kx1



10



Dx10




Fx2



Jx1





11



Ax4




12



Zx4




13



Nx1	
Ox1	

14



Nx1	
Px1	