

















A x 32 ϕ 6 x $\frac{30}{1.2}$


B x 4 C x 4 D x 20 E x 8 F x 14 $\phi 6 \times \frac{15}{0.6} \quad \phi 6 \times \frac{40}{1.6} \quad \phi 4 \times \frac{25}{1.0} \quad \phi 5 \times \frac{40}{1.6} \quad \phi 7 \times \frac{70}{2.8}$

G x 1





1 x 2











H x 10

 $\phi 4 \times \frac{30}{1.2}$

J x 2

K x 16

 ϕ 3 x $\frac{20}{0.8}$

L x 2

M x 20

$$\phi 3 \times \frac{16}{0.6}$$















N x 4 Ø8 x 25 1

O x 1

P x 2

 $\phi 4 \times \frac{40}{1.6}$

Q x 4

R x 14



T x 2






U x 2




V x 4




W x 4









































C x 2	$\phi 6 \times \frac{40}{1.6}$
Dx4	$\phi 4 \times \frac{25}{1.0}$





V	



D x 10		$\phi 4 \times \frac{25}{1.0}$
V x 4		
M x 8	*	ϕ 3 x $\frac{16}{0.6}$
T x 2	\bigcirc	



